

Sharp Shoot R



Sharp Shoot R Precision Products Inc.

Box 171

Paola, Kansas 66071

785-883-4444 phone

785-883-2525 fax

email= gethelp@sharpshootr.com

www.sharpshootr.com

Technical Bulletin 722:

THE DIFFERENCE BETWEEN 'WIPE OUT', 'PATCH OUT', & 'TACTICAL ADVANTAGE'?

1. **'WIPE OUT'** was the first foaming bore cleaner; sold since 97. The foam may be applied to the muzzle or the breach. WIPE OUT revolutionized bore cleaning since it is still the only 100% brushless cleaner, which dissolves all fouling. It contains no acid, and no ammonia. Contains anti-corrosives that protect the bore without the use of oil. Therefore making fouling shots unnecessary. Color indicators show what is being dissolved. COPPER is blue. CARBON is brown. POWDER FOULING is always grey or black. Working time from 10 minutes to 72 hours. Many times with a heavily fouled barrel, copper blue will show as the first foam at the muzzle.

(Read WIPE OUT technical bulletin

<http://www.sharpshootr.com/wp-content/uploads/2013/10/Instructions-WIPE-OUT-2013-.pdf>)

2. **'PATCH OUT'** was developed for those shooters who were more comfortable with conventional application methods. Still has all the features of Wipe Out, but is applied with a nylon brush. This makes 'PATCH OUT' foam like Wipe Out. We want bubbles of air like Wipe Out because they excite the chemicals making them 3 times more efficient than other cleaners. Convenient application is the key.

(Read PATCH OUT technical bulletin

<http://www.sharpshootr.com/wp-content/uploads/2013/10/Instructions-PATCH-OUT-JAN-2014.pdf>)

3. **'TACTICAL ADVANTAGE'** developed solely for the Stoner designed family of M-16, M-4, and AR-15's and all those clones of these firearms. These firearms by design are prone to huge amounts of fouling in the gas system, primarily the bolt carrier. The bolt carrier can become encrusted with fouling which prevents the intended function. 'TACTICAL ADVANTAGE' can clean the gas system and the bolt carrier, as well as functioning like Wipe Out, Patch Out.

(Read TACTICAL ADVANTAGE technical bulletin

<http://www.sharpshootr.com/wp-content/uploads/2013/10/Instructions-TACTICAL-ADVANTAGE-2013-1.pdf>)

4. **'ACCELERATOR'** developed as an adjunct for those shooters with COPPER problems. 'ACCELERATOR' is not a cleaner. It will when used with Wipe Out, Patch Out, or Tactical Advantage, dissolve twice the amount of COPPER, within any period. Use it when you don't have time with a firearm you know has a history of COPPER fouling. **DON'T**

USE IT IF YOU DON'T NEED IT.

5. USING THE 'PROOF TEST'

(Read <http://www.sharpshootr.com/wp-content/uploads/2013/10/HOW-TO-USE-THE-PROOF-TEST-Copy.pdf>)

The **"PROOF TEST"** is used any time you need to know what condition the barrel is in. We use the **"PROOF TEST"** when we need to know if a firearm is clean or needs to be cleaned.

1. **TO RUN A "PROOF TEST"** you put an application of either **WIPE-OUT™** or **PATCH-OUT™** in the barrel of the gun you wish to test. Let this application set in the barrel around 10 minutes. Push a single patch thru the bore. If there is any fouling present in this barrel it will show up immediately on the patch. 10 minutes is long enough for the chemicals in our formula to react to any sort of fouling.

No color or a clean white patch is evidence of a clean barrel.

We use this test any time we are not sure of the condition of the bore.....or to determine if we need to re-apply either **WIPE-OUT™** or **PATCH-OUT™**.